Determining the end face of the optical cable



Overview

Methods for Identifying Optical Cable End FacesStandards such as IEC 61300-3-47, Basic test and measurement procedures for end face geometry of PC/APC sphe.

Key Takeaways

The end face of an optical cable can be identified by inspecting its polished surface, fiber core, cladding, and ferrule using a fiber microscope or video inspection scope according to IEC standards. Key Steps to Identify an Optical Fiber End Face1. Determine the Connector Type Optical fibers may have different connector types, such as LC, SC, FC, ST, or MPO/MTP.

Each connector has a ferrule that holds the fiber and a polished end face. The end face may be PC (Physical Contact), UPC (Ultra Physical Contact), or APC (Angled Physical Contact), which affects the curvature and angle of the fiber tip.

PC and UP

C are dome-shaped, while APC has an 8° angle to reduce back reflection. 2. Inspect the End Face Using Proper Tools Use a fiber microscope or handheld video scope to examine the end face.

These tools allow you to see the fiber core, cladding, ferrule surface, and epoxy region. Video scopes are preferred for live fibers to avoid exposure to infrared light. Advanced scopes can provide autofocus, automatic centering, and pass/fail analysis.

3. Check for Cleanliness and Defects Inspect for dust, scratches, pits, chips, or cracks.

© 2026 CGWEB NETWORK INFRASTRUCTURE - All rights reserved

The IE

C 61300-3-35 standard defines four concentric zones for inspection: Zone A (core) – most critical for signal transmissionZone B (cladding) – affects mode field confinementZone C (adhesive) – tolerable within limitsZone D (ferrule contact area) – tolerable if not extending into the fiber 4.

Evaluate End-

Face Geometry Key parameters include: Radius of Curvature (ROC) – ensures proper contact between fibersApex Offset – distance from the highest point of the ferrule to the fiber core centerFiber Height – relative position of the fiber core to the ferrule surface; protruding or recessed cores can affect insertion loss 5.

Follow Standardized Criteria Use IE

C 61300-3-35 for visual inspection and cleanliness grading, and IEC 61755 for geometry measurements. Automated inspection tools can map images to these standards and provide consistent pass/fail results. 6.

Safety Considerations Never look directly into a fiber carrying optical power, especially infrared, as it can be invisible and harmful. Use video scopes or protective filters. By following these steps, you can reliably identify and assess the end face of an optical cable, ensuring optimal performance and minimizing signal loss.

Article Content

Methods for Identifying Optical Cable End Faces

Standards such as IEC 61300-3-47, Basic test and measurement procedures for end face geometry of PC/APC spherically polished ferrules using interferometry, and a series of IEC 61755 standards

Fiber Optic Terminus End Face Quality Standards

Figure 7 depicts a typical end face of single mode and multimode terminus and fiber end face regions. The closer one is to the core or region A, the more stringent the requirements are for a pristine

Fiber Endface Inspection – connectors, bare fiber ends,

This article explains the critical importance of fiber endface inspection for maintaining performance and reliability in fiber optics.

What Makes a Quality Fiber End Face?

© 2026 CGWEB NETWORK INFRASTRUCTURE - All rights reserved

Fiber optics utilizes pulses of light to transmit data across long distances at high speeds. The physical connection point where light enters or exits the fiber, known as the end face, is the most

MEASUREMENT OF END FACE GEOMETRY ON FIBER OPTIC

Interferometry uses light waves to measure the surface in 3 dimensions. This makes it the preferred method for analyzing fiber optic end faces because it provide immediate information on the entire

Fiber Optic Terminus End Face Quality Standards

Good fiber optic performance relies on connectors that are manufactured properly. Specifically, optimal optical performance requires that the mating surfaces of the fiber optic termini be

Cable Assemblies with ClearCurve Multimode Fiber: End-Face

This Applications Engineering Note (AE Note) discusses the methods available for visualizing connector end-faces that contain Corning® ClearCurve® OM3/OM4 multimode fiber (also referred to as “ultra

A Closer Look at Fiber Optic Cable Assemblies

We tested each assembly to Siemon Internal specifications as well as TIA and IEC standards for end face geometry, optical performance, cleanliness and mechanical reliability.

Easier fiber end face inspections: Changes to IEC 61300-3-35

It''s crucial to inspect, clean, and reinspect fiber end faces before mating connectors — whether on patch cords and trunks within the network or on the test reference cord you connect to

Fiber Optic Terminus End Face Quality Standards

Fiber Optic Terminus End Face Quality Standards Introduction Good fiber optic performance relies on connectors that are manufactured properly. Specifically, optimal optical performance requires that the

Fiber Cable End-Face Inspection: What Is It?

The image below shows two dirty end faces and one clean end face through a fiber microscope. However, even if you get what appears to be a clean end face through a microscope,

ASTM International | ASTM

Over 13,000 ASTM standards operate globally. Defined and set by us, they improve the lives of millions every day. ASTM provides the standards and solutions you

© 2026 CGWEB NETWORK INFRASTRUCTURE - All rights reserved

Cleaning Fiber Optic End Faces: Contamination Sources and

Fiber optic cable runs are extremely susceptible to things that block light--especially at the very end of that run. In fact, that is the number one reason for failed or poorly performing fiber optic

The Fiber Optic Association

Other groups may have fiber optic standards also: ANSI is the governing bodies for standards in the US, NIST provides primary standards, IEEE has standards for networks like Ethernet, IWCS has

Differences between the 3 Common End-face Types

Different end-face morphologies determine the quality of fiber transmission, mainly in insertion loss and return loss. □1□Insertion Loss, Insertion Loss refers to the optical signal through the fiber optic

What is Fiber Optic Endface Geometry? Part 1 | Promet Optics

This is the 1st of a 3 part post from the white paper entitled “Fiber Optic 3D Metrology”. We will define and lay out the necessity of measuring endface geometry as well as a conceptual

Ferrule and endface Geometry

Thanks to high-tech equipment including modern interferometers and electric microscope, a precise analysis concerning end face geometry parameters of ferrules is possible. Therefore, it is the

Fiber Endface Inspection – connectors, bare fiber ends,

Definition: inspection of the quality of fiber endfaces, e.g. before splicing Alternative term: fiber inspection probes Category: fiber optics and waveguides Concept

Related Video Reference

This video was associated with the source search result. Verify technical details against current product documentation and project requirements.

© 2026 CGWEB NETWORK INFRASTRUCTURE - All rights reserved

Contact Us

Continue your research online:

Website: https://cgweb.co.za
Technical inquiry: https://cgweb.co.za/project-enquiry.html

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

© 2026 CGWEB NETWORK INFRASTRUCTURE - All rights reserved